

DIRECT REPLACEMENT

DIRECT REPLACEMENT

DIRECT REPLACEMENT

DIRECT REPLACEMENT

SILICON CARBIDE

SILICON CARBIDE

SILICON CARBIDE

SILICON CARBIDE

IGN-401



TRUE START[®] Hot Surface Igniter



Replaces:

41-401	767A-356	D99182,
201A	767A-369	B1336102
271A	DS401	10041601

18 month warranty



DIRECT
REPLACEMENT

SILICON
CARBIDE



800.995.2222
www.diversitech.com

L46-271

